#### DEPARTMENT OF TRANSPORTATION

**Federal Aviation Administration** 

**14 CFR Part 39** 

[Docket No. FAA-2022-1653; Project Identifier MCAI-2022-01193-T]

**RIN 2120-AA64** 

Airworthiness Directives; De Havilland Aircraft of Canada Limited (Type

Certificate Previously Held by Bombardier, Inc.) Airplanes

**AGENCY:** Federal Aviation Administration (FAA), DOT.

**ACTION:** Notice of proposed rulemaking (NPRM).

SUMMARY: The FAA proposes to adopt a new airworthiness directive (AD) for certain De Havilland Aircraft of Canada Limited Model DHC-8-400 series airplanes. This proposed AD was prompted by reports of flap power unit (FPU) pressure switch failures resulting in flap inoperative events. This proposed AD would require replacing the FPU pressure switch or the FPU. This proposed AD would also prohibit the installation of affected parts. The FAA is proposing this AD to address the unsafe condition on these products.

**DATES:** The FAA must receive comments on this proposed AD by [INSERT DATE 45 DAYS AFTER DATE OF PUBLICATION IN THE FEDERAL REGISTER].

**ADDRESSES:** You may send comments, using the procedures found in 14 CFR 11.43 and 11.45, by any of the following methods:

- Federal eRulemaking Portal: Go to regulations.gov. Follow the instructions for submitting comments.
  - Fax: (202) 493-2251.
- Mail: U.S. Department of Transportation, Docket Operations, M-30, West Building Ground Floor, Room W12-140, 1200 New Jersey Avenue SE, Washington, DC

- Hand Delivery: Deliver to Mail address above between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays.

  \*\*AD Docket\*\*: You may examine the AD docket at regulations.gov under Docket No. FAA-2022-1653; or in person at Docket Operations between 9 a.m. and 5 p.m., Monday through Friday, except Federal holidays. The AD docket contains this NPRM, the mandatory continuing airworthiness information (MCAI), any comments received, and other information. The street address for Docket Operations is listed above.
- *Material Incorporated by Reference:*
- For service information identified in this NPRM, contact De Havilland Aircraft of Canada Limited, Dash 8 Series Customer Response Centre, 5800 Explorer Drive, Mississauga, Ontario, L4W 5K9, Canada; telephone North America (toll-free): 855-310-1013, Direct: 647-277-5820; email thd@dehavilland.com; website dehavilland.com.
- You may view this service information at the FAA, Airworthiness Products

  Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For

  information on the availability of this material at the FAA, call (206) 231-3195.

  FOR FURTHER INFORMATION CONTACT: Gabriel Kim, Aerospace Engineer,

  Mechanical Systems and Administrative Services Section, FAA, New York ACO

  Branch, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone

  (516) 228-7300; email 9-avs-nyaco-cos@faa.gov.

#### **SUPPLEMENTARY INFORMATION:**

#### **Comments Invited**

The FAA invites you to send any written relevant data, views, or arguments about this proposal. Send your comments to an address listed under ADDRESSES. Include "Docket No. FAA-2022-1653; Project Identifier MCAI-2022-01193-T" at the beginning of your comments. The most helpful comments reference a specific portion of the

proposal, explain the reason for any recommended change, and include supporting data.

The FAA will consider all comments received by the closing date and may amend this proposal because of those comments.

Except for Confidential Business Information (CBI) as described in the following paragraph, and other information as described in 14 CFR 11.35, the FAA will post all comments received, without change, to regulations.gov, including any personal information you provide. The agency will also post a report summarizing each substantive verbal contact received about this NPRM.

### **Confidential Business Information**

CBI is commercial or financial information that is both customarily and actually treated as private by its owner. Under the Freedom of Information Act (FOIA) (5 U.S.C. 552), CBI is exempt from public disclosure. If your comments responsive to this NPRM contain commercial or financial information that is customarily treated as private, that you actually treat as private, and that is relevant or responsive to this NPRM, it is important that you clearly designate the submitted comments as CBI. Please mark each page of your submission containing CBI as "PROPIN." The FAA will treat such marked submissions as confidential under the FOIA, and they will not be placed in the public docket of this NPRM. Submissions containing CBI should be sent to Gabriel Kim, Aerospace Engineer, Mechanical Systems and Administrative Services Section, FAA, New York ACO Branch, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone (516) 228-7300; email 9-avs-nyaco-cos@faa.gov. Any commentary that the FAA receives which is not specifically designated as CBI will be placed in the public docket for this rulemaking.

#### Background

Transport Canada, which is the aviation authority for Canada, has issued AD CF-2022-52, dated September 1, 2022 (Transport Canada AD CF-2022-52) (also

referred to as the MCAI), to correct an unsafe condition for certain De Havilland Aircraft of Canada Limited Model DHC-8-401 and -402 airplanes. The MCAI states there have been increasing reports of FPU pressure switch failures, part number (P/N) 150135-1 or P/N 162660-1, over the past year leading to a high number of flap inoperative events in flight and on the ground. An investigation has determined the root cause to be a deformation of the FPU pressure switch internal mechanism due to hydraulic pressure spikes. If not corrected, a failed FPU pressure switch could lead to a failure of the FPU resulting in abnormal flap landings and increased landing distances, which could require the use of emergency landing procedures and/or airfield diversions. The improved pressure switch, P/N 162660-2, has a restrictor insert in the pressure switch inlet.

You may examine the MCAI in the AD docket at regulations.gov under Docket No. FAA-2022-1653.

#### **Related Service Information Under 1 CFR Part 51**

The FAA reviewed De Havilland Aircraft of Canada Limited (DHC) Service Bulletin (SB) 84-27-75, dated June 23, 2022 (SB 84-27-75). SB 84-27-75 is a combined service bulletin consisting of DHC SB 84-27-75 and Collins Aerospace SB 27-0029, Basic Issue, dated June 13, 2022. This service information specifies procedures for replacing FPU P/N C148656-1 or C148656-2 with a new FPU P/N C148656-3, or replacing FPU pressure switch P/N 150135-1 or 162660-1 within the FPU with a new pressure switch P/N 162660-2 and re-identifying the FPU as P/N C148656-3. This material is reasonably available because the interested parties have access to it through their normal course of business or by the means identified in ADDRESSES.

### **FAA's Determination**

This product has been approved by the aviation authority of another country and is approved for operation in the United States. Pursuant to the FAA's bilateral agreement with the State of Design Authority, it has notified the FAA of the unsafe condition

described in the MCAI described above. The FAA is issuing this NPRM after determining that the unsafe condition described previously is likely to exist or develop in other products of the same type design.

# Proposed AD Requirements in this NPRM

This proposed AD would require accomplishing the actions specified in the service information already described. This proposed AD would also prohibit the installation of affected parts.

## **Costs of Compliance**

The FAA estimates that this AD, if adopted as proposed, would affect 53 airplanes of U.S. registry. The FAA estimates the following costs to comply with this proposed AD:

### **Estimated costs for required actions**

Labor cost	Parts cost	Cost per product	Cost on U.S. operators
Up to 6 work-hours X \$85 per hour = Up to \$510	Up to \$3,000	Up to \$3,510	Up to \$186,030

The FAA has included all known costs in its cost estimate. According to the manufacturer, however, some or all of the costs of this proposed AD may be covered under warranty, thereby reducing the cost impact on affected operators.

### **Authority for this Rulemaking**

Title 49 of the United States Code specifies the FAA's authority to issue rules on aviation safety. Subtitle I, section 106, describes the authority of the FAA Administrator. Subtitle VII: Aviation Programs, describes in more detail the scope of the Agency's authority.

The FAA is issuing this rulemaking under the authority described in Subtitle VII, Part A, Subpart III, Section 44701: General requirements. Under that section, Congress charges the FAA with promoting safe flight of civil aircraft in air commerce by

prescribing regulations for practices, methods, and procedures the Administrator finds necessary for safety in air commerce. This regulation is within the scope of that authority because it addresses an unsafe condition that is likely to exist or develop on products identified in this rulemaking action.

### **Regulatory Findings**

The FAA determined that this proposed AD would not have federalism implications under Executive Order 13132. This proposed AD would not have a substantial direct effect on the States, on the relationship between the national Government and the States, or on the distribution of power and responsibilities among the various levels of government.

For the reasons discussed above, I certify this proposed regulation:

- (1) Is not a "significant regulatory action" under Executive Order 12866,
- (2) Would not affect intrastate aviation in Alaska, and
- (3) Would not have a significant economic impact, positive or negative, on a substantial number of small entities under the criteria of the Regulatory Flexibility Act.

### List of Subjects in 14 CFR Part 39

Air transportation, Aircraft, Aviation safety, Incorporation by reference, Safety.

### **The Proposed Amendment**

Accordingly, under the authority delegated to me by the Administrator, the FAA proposes to amend 14 CFR part 39 as follows:

# PART 39 - AIRWORTHINESS DIRECTIVES

1. The authority citation for part 39 continues to read as follows:

Authority: 49 U.S.C. 106(g), 40113, 44701.

# § 39.13 [Amended]

2. The FAA amends § 39.13 by adding the following new airworthiness directive:

De Havilland Aircraft of Canada Limited (Type Certificate Previously Held by

**Bombardier, Inc.):** Docket No. FAA-2022-1653; Project Identifier MCAI-2022-01193-T.

### (a) Comments Due Date

The FAA must receive comments on this airworthiness directive (AD) by [INSERT DATE 45 DAYS AFTER DATE OF PUBLICATION IN THE FEDERAL REGISTER].

### (b) Affected ADs

None.

## (c) Applicability

This AD applies to De Havilland Aircraft of Canada Limited (Type Certificate previously held by Bombardier, Inc.) Model DHC-8-401 and -402 airplanes, certificated in any category, serial numbers 4001 and 4003 through 4633 inclusive.

### (d) Subject

Air Transport Association (ATA) of America Code: 27, Flight Controls.

### (e) Unsafe Condition

This AD was prompted by reports of flap power unit (FPU) pressure switch failures resulting in flap inoperative events. The FAA is issuing this AD to address FPU pressure switch failures. The unsafe condition, if not addressed, could result in abnormal flap landings and increased landing distances, which could require the use of emergency landing procedures and/or airfield diversions.

# (f) Compliance

Comply with this AD within the compliance times specified, unless already done.

# (g) Requirements

Within 8,000 flight hours or 48 months after the effective date of this AD, whichever occurs first: Do the actions specified in either paragraph (g)(1) or (2) of this AD.

- (1) Replace FPU part number (P/N) C148656-1 or C148656-2 with P/N C148656-3 in accordance with Section 3.B. paragraph (1), of the Accomplishment Instructions of De Havilland Aircraft of Canada Limited Service Bulletin 84-27-75, dated June 23, 2022.
- (2) Replace FPU pressure switch P/N 150135-1 or 162660-1 with P/N 162660-2 in accordance with Section 3.B. paragraph (2), of the Accomplishment Instructions of De Havilland Aircraft of Canada Limited Service Bulletin 84-27-75, dated June 23, 2022, and reidentify the FPU as P/N C148656-3 in accordance with Section 3.C of the Accomplishment Instructions of Collins Aerospace S B 27-0029, Basic Issue, dated June 13, 2022.

Note 1 to paragraph (g): The service information referred to De Havilland Aircraft of Canada Limited (DHC) Service Bulletin (SB) 84-27-75, dated June 23, 2022, is a combined service bulletin consisting of DHC SB 84-27-75 and Collins Aerospace SB 27-0029, Basic Issue, dated June 13, 2022.

#### (h) Parts Installation Prohibition

As of the effective date of this AD, do not install a FPU having P/N C148656-1 or C148656-2 or a FPU pressure switch having P/N 150135-1 or 162660-1.

### (i) Additional AD Provisions

The following provisions also apply to this AD:

(1) Alternative Methods of Compliance (AMOCs): The Manager, New York ACO Branch, FAA, has the authority to approve AMOCs for this AD, if requested using the procedures found in 14 CFR 39.19. In accordance with 14 CFR 39.19, send your request to your principal inspector or responsible Flight Standards Office, as appropriate. If sending information directly to the manager of the certification office, send it to ATTN: Program Manager, Continuing Operational Safety, FAA, New York ACO Branch, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone (516) 228-7300. Before

using any approved AMOC, notify your appropriate principal inspector, or lacking a principal inspector, the manager of the responsible Flight Standards Office.

(2) Contacting the Manufacturer: For any requirement in this AD to obtain instructions from a manufacturer, the instructions must be accomplished using a method approved by the Manager, New York ACO Branch, FAA; or Transport Canada; or De Havilland Aircraft of Canada Limited's Transport Canada Design Organization Approval (DOA). If approved by the DOA, the approval must include the DOA-authorized signature.

## (j) Additional Information

- (1) For related information, refer to Transport Canada AD CF-2022-52, dated September 1, 2022. This Transport Canada AD may be found in the AD docket at regulations.gov under Docket No. FAA-2022-1653.
- (2) For more information about this AD, contact Gabriel Kim, Aerospace Engineer, Mechanical Systems and Administrative Services Section, FAA, New York ACO Branch, 1600 Stewart Avenue, Suite 410, Westbury, NY 11590; telephone (516) 228-7300; email 9-avs-nyaco-cos@faa.gov.

### (k) Material Incorporated by Reference

- (1) The Director of the Federal Register approved the incorporation by reference (IBR) of the service information listed in this paragraph under 5 U.S.C. 552(a) and 1 CFR part 51.
- (2) You must use this service information as applicable to do the actions required by this AD, unless this AD specifies otherwise.
- (i) De Havilland Aircraft of Canada Limited Service Bulletin 84-27-75, dated June 23, 2022.
  - (ii) [Reserved]

- (3) For service information identified in this AD, contact De Havilland Aircraft of Canada Limited, Dash 8 Series Customer Response Centre, 5800 Explorer Drive, Mississauga, Ontario, L4W 5K9, Canada; telephone North America (toll-free): 855-310-1013, Direct: 647-277-5820; email thd@dehavilland.com; website dehavilland.com.
- (4) You may view this service information at the FAA, Airworthiness Products Section, Operational Safety Branch, 2200 South 216th St., Des Moines, WA. For information on the availability of this material at the FAA, call (206) 231-3195.
- (5) You may view this service information that is incorporated by reference at the National Archives and Records Administration (NARA). For information on the availability of this material at NARA, email fr.inspection@nara.gov, or go to: www.archives.gov/federal-register/cfr/ibr-locations.html.

Issued on December 19, 2022.

Christina Underwood, Acting Director, Compliance & Airworthiness Division, Aircraft Certification Service.

[FR Doc. 2022-27876 Filed: 12/22/2022 8:45 am; Publication Date: 12/23/2022]